## Highways Annex A – dated 18 June 2025.

| Issue   | Date<br>Reported                                   | By<br>Whom | То                 | Progress  |
|---|--|------------|--------------------|---|
| Parish Steward Visits 2025  | Next Visits<br>2025<br>July 24th                   |            |                    | Any issues to be reported to KW for<br>Parish Steward's next visit.   |
| West Tockenham, Flooding. C120 Main Village   | Aprl 23<br>Update<br>May 2025                      | DK         | wc                 | Blocking gully investigations at<br>Field view indicates a link to main<br>Village flooding issues.<br>Work carried out 21 <sup>st</sup> Nov 24<br>however main Village flooded after<br>this during 'Storm Bert' Nov 24.<br>Following work at Field View and<br>Vactor visit situation to be<br>monitored. |
| Tockenham Wick, Flooding / Road surface degradation.  | May 2025   | KW         | WC                 | Further discussions have taken<br>place (KW AB MC)<br>MC to provide written options.  |
| Tockenham Corner / Primrose Hill - Flooding<br>Request for review of findings following WC<br>Drainage Team site visit July 2024.   | Nov 2024<br>Update<br>May 2025                     | KW         | WC<br>AB           | Report from Review Site Visit May<br>2025.<br>Highways and Drainage (MC & DE)<br>Indicate due to the nature of the<br>road, a scheme in this location<br>would be unlikely to meet sufficient<br>criteria to be prioritised.  |
| Potholes Mermaid Corner C120 junction with<br>Preston Lane Case No 00213815.  | Feb 2025   | KW         | wc                 | Works carried out 13 Feb 25.<br>Not completed – New Potholes<br>developed since.  |
| Opposite Field View - No 1 Tockenham. Blocked<br>drain/gully. Road area by sewage plant now<br>breaking up due to constant flow of water.<br>Issue linked to main Village flooding. SEE ABOVE                           | Sept 23<br>Updated<br>May 2025                     | KW         | wc                 | Case No.00125935.<br>Investigation Aug 24 shows<br>fractured pipe. Works carried out<br>21 <sup>st</sup> Nov 24.<br>Monitor Autumn Winter 2025.   |
| Flooding – south of Rowley Copse C120.<br>Culvert blasted. Awaiting possible watercourse re-<br>direction work by landowner east side of culvert.<br>NOTE – Concerns exist that this may impact on<br>Tockenham Corner. | Nov 24<br>Updated<br>22 <sup>nd</sup> May<br>2025. | KW         | WC                 | Advice from WC drainage (D<br>Everett). Any watercourse digging<br>between C120 and C130 would<br>likely result in volume /speed of<br>water approaching Tockenham<br>Corner increasing and making any<br>potential flood worse. <b>Case closed</b> .   |
| Junction with Preston Lane C130. – Mermaid<br>Corner. Continuous flooding causing serious<br>deterioration of road surface.   | May 2025   | KW         | WC                 | CCTV Survey of total drainage<br>system. Road surface works<br>Mermaid to Breach Lane following<br>drainage remedial work.<br>Action – Drainage and Highways<br>Teams.  |
| Pothole case No Greenway 148264<br>Orchard Lane – 148105 and 148101<br>Greenway 144238.   | Jan 24   | KW         | My<br>Wilts<br>App | Reported.<br>Awaiting repair/investigation.<br>Ongoing as C class road – low<br>priority.   |
| A3102 Tockenham Corner – Culvert/road erosion   | May 2025   | KW         |                    | CCTV Investigation required by<br>Highways (M Cook) of Culvert and<br>road erosion. High Priority.  |